

Oil Field Environmental Incident Summary

Incident: 20140119124101 **Date/Time of Notice:** 01/19/2014 12:10

Responsible Party: Arrow Pipeline, LLC

Well Operator:

Well Name:

Field Name:

Well File #: 0

Date Incident: 1/16/2014

Time Incident: 11:37

Facility ID Number:

County: DUNN

Twp: 148

Rng: 94

Sec: 6

Qtr: NW SE

Location Description: THIS IS UPDATE TO VERBAL NOTIFICATION MADE 01/16/2014 Pipeline pig receiver pad located on Three Affiliated Tribes property

Submitted By: Don Butler

Received By:

Contact Person: Don Butler

Crestwood Midstream Prtrs LP, 801 Cherry Street

Suite 3800/Unit 20

Fort Worth, TX 76001

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1600 Feet

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: Yes

	Spilled	Units	Recovered	Units	Followup	Units
Oil	50	barrels	0	barrels		
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None observed

Areal Extent:

wind driven spray approx 1600-ft

Potential Environmental Impacts:

Surface impact to soil.

Action Taken or Planned:

Emergency response activated, property owner notified, responders mobilized to site, source shut in, remedial actions initiated. Verbal Notification made to NDIC and ND-Department of Health 01/16/2014 and NRC on 01/19/2014. Remedial operations nearing completion

Wastes Disposal Location: per regulatory requirements

Agencies Involved:**Updates**

Date: 1/21/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from a valve/pipeline leak, sprayed approximately 1600 feet off the location, impacting a nearby mobile home and other property. Report was received through ND DES on 1/16/2014, by verbal notification from the report contact person. It was assumed that, since the incident happened within MHA Nation, that it was reported there as well, but the report does not state that. Therefore, this report is being forwarded to MHA Environmental and BIA.